BUILDING SAFETY CERTIFICATE

No. 248 2015

Dated: 23-06-2025

It is certified that the existing building ST. JOSEPH'S HIGHER SECONDARY SCHOOL Primary School (Bldg. No. 101), High School Building (Bldg. No. 102-A) and Admin Building (Bldg. No. 102-B) in Gat No. 158/3- at Village- Handinimgaon, Tal-Newasa, Dist. - Ahmednagar are having block(s)/Floor(s) as per details below:

Details of Block(s) in School	Block	Block
	(A)	(B)
No. of Floors (s) in the Block	Ground-1	Ground-1
	Upper-2	Upper-2

- 1. Government will not be held responsible if the construction is poor or if an accident occurs.
- 2. The concerned Architect and Structural Engineer will be responsible for the said construction competence.
- 3. If the construction is not as approved by the Town planning office, this office will not be responsible for it.
- 4. An inspection of the building construction should be done every year by the competent authority.
- 5. Firefighting should be inspected every year before the commencement of school by the competent authority.

Issued on 23-06-2025 at Newara by

*Strike out whichever is not applicable. In case of block is more than six, use a separate sheet for details.

Signature with Seal:Sub Divisional Officer
Z.P.P.W.Sub-Division, Newasa

Designation: Sub-division office

Name & Address of Department/ Office:

Principal

Skebello

St Joseph's Higher Secondary School Handinimgaon, Newasa, Ahmednagar, Maharashtra - 414 603 Manager

St. Joseph's Higher Secondary School Handinimgaon, Newasa, Ahmednagar, Maharashtra - 414603